




# THREE PHASE FULL WAVE RECTIFIER (POLYPHASE RECTIFIERS)

## MODEL-RECT05

This trainer has been designed with a view to provide practical and experimental knowledge of Three Phase Full wave Rectifier.



### SPECIFICATIONS

1. Power supply requirement : 440V AC, 3 Phase.
2. Following parts provided on Single PCB with connecting terminals.  
SCR : 3 Nos.  
Power Diode : 3 Nos.
3. Load Resistors : 1K 10W, 1K 10W with 100mh Coil, 1000/35 EC, 0.1 PPC
4. Three Mains Transformer with step down AC Voltages : 0-30V/250 mA.
5. Accessories : 2 mm patch cord - 4 Nos.
6. Accessories required : Laboratory Multimeter - Simpson 260 or better.  
General-purpose double beam oscilloscope. 380-440V, 3 Phase A.C. mains, three wire input.

In keeping view of SIGMA policy of continuous development and improvement, the Specifications may be changed without prior notice or obligation.

**Sigma Trainers and Kits**  
E-113, Jai Ambe Nagar,  
Near Udgam School,  
Thaltej,  
AHMEDABAD - 380054.  
INDIA.

**Phone(O): +91-79-26852427/ 26850829**  
**Phone(F): +91-79-26767512/ 26767648**  
**Fax : +91-79-26840290/ 26840290**  
**Mobile : +91-9824001168**  
**Email : sales@sigmatrainers.com**  
**: sigmatrainers@sify.com**  
**Web : www.sigmatrainers.com**

**Dealer:-**